

# X-Plane 12 Pilot Checkride Challenge Checklist

## Challenge Checklist

- [X] Preflight and Taxi Complete
- [X] Normal Takeoff and Climb
- [X] Straight and Level Flight
- [X] Standard Rate Turns
- [X] Steep Turns at 45 Degrees
- [X] Slow Flight (Full Flaps)
- [X] Power-Off Stall and Recovery
- [ ] Ground Reference Maneuvers (Optional)
- [X] Simulated Engine Failure
- [X] Normal Landing
- [X] Short Field Landing
- [X] Soft Field Landing

## PASS Tolerances

- Altitude: +/- 100 ft
- Airspeed: +/- 10 KIAS
- Heading: +/- 10 degrees
- Steep Turn Bank: +/- 5 degrees
- Landing Accuracy: +/- 400 ft (normal), +/- 200 ft (short field)

## Instructor Notes

Overall Technique: \_\_\_\_\_

Checklist Discipline: \_\_\_\_\_

Radio Comms (if used): \_\_\_\_\_

Best Glide Selection: \_\_\_\_\_

**X-Plane 12 Pilot Checkride Challenge Checklist**

Landing Control: \_\_\_\_\_

Final Grade: PASS   MARGINAL   RETRY